RECEIVED DHSS Breach Alcohol Program
By Carol Day at 4:03 pm, Mar 03, 2010

A81444					
Complete this report in duplicate at the is repaired. Send copy to Department of H	time of the regular ealth; retain original	monthly preventive m in department file.	aintenance c	heck, ar	nd whenever instrumen
DATAMASTERS.1 204112					INSPECTION OI - 2010
LOCATION OF INSTRUMENT (STREET AND CITY) BROX	KFIELD POLICE	E DEPARTMENT	r —	TIME OF I	NSPECTION
CHECKLIST: Place a check () to the lef	t of each item if four		r if operating	within e	stablished limits. (Write
in observed values where determined.) Und	checked items must I	pe corrected before usi	ing instrumer	it.	
DIAGNOSTIC CHECK (PRINTOUT AT	rtached)				
COMPUTER		DETECTOR			
PROGRAM		FILTERS			
HEATERS SAMPLE CHAMBER .	50 _{°c}	QUARTZ STAND	DARD		
FLOW DETECTOR		CALIBRATION			
PUMP HIGH SPEED		PRINTER			
M INDICATOR LIGHTS					
TIME AND DATE					
SIMULATOR TEMPERATURE (34 °C ±	= 0.2°C) 34°C				
CALIBRATION CHECK -					
Run three tests using a standard solu	ution All three tests	s must be within ± 5°	% of the stai	ndard va	alue and must have a
spread of .005 or less. Check the box RECIRCULATION PUMP)					
M 0.100% STANDARD - MUST READ	BETWEEN 0.095% ar	nd 0.105% INCLUSIVE			
0.040% STANDARD - MUST READ ONLY ONE STANDARD IS TO BE US					
TEST 1 # 1099	TEST 2		TEST 3	F 1/2	<u></u>
	<u> </u>	all the of the column and the other than the column and the column	[,,,	
PERFORM R.F.I. TEST (PRINTOUT AT	TAGRED				
NUMBER OF REFUSALS, SINCE LAST FOLLOWS: (DO NOT INCLUDE SIM		PORT, AND NUMBER (OF BREATH	TESTS I	N EACH RANGE AS
REFUSALS Ø (004) Ø " (.1	0509) Ø	(.1014)	(.1519)	l	(Over .19)
List any new parts and describe any altera		that was made to rest	ore the instr	ument to	o operate satisfactorily
and within established limits (use other side MEETS DEPARTMENT OF		tandards			
7.02					
REPCO MARKETING, INC		LOT # 09	002		
VAPOR SOLUTION ->. 100		EXP: 08-	31-2011		
	The state of the season was set to	n ar a de la carre de la c	gilisa eri el terresciente escel		
INSPECTING OFFICER	राम का के देश आवश है। या जिल्हा कि कि कि कि	PRINT NAME			
Kan tosso		KEID T	FESS	LEK	
TYPE II PERMIT NUMBER/EXPIRATION DATE 02-0	5-2012	660-385-	2132		

CERTIFICATE OF ANALYSIS

MANUFACTURER AND SUPPLIER: RepCo Marketing, Inc. LOT NUMBER: 09002 EXPIRATION DATE: August 31, 2011 at 11:59 p.m.

RepCo Marketing, Inc. certifies the following:

RepCo Marketing, Inc. manufactured, tested and supplied Lot Number <u>09002</u> of Alcohol Certified Solution for simulators. Random samples of said lot number were analyzed by an independent laboratory utilizing a gas chromatograph and found to contain <u>.1206</u> gms/dl +/-.003 gms/dl wt/vol ethanol (95% Confidence).

The alcohol and distilled water used in the solution were found to be free of any interfering substance.

This solution will produce a vapor alcohol value of <u>.100</u> +/-3% gms/210L Breath when heated to 34 Degrees Celsius +/-0.2 Degrees Celsius in a simulator (95% Confidence).

The date of manufacture for this lot number is **September 1, 2009.**The expiration date for this lot number is **August 31, 2011** at 11:59 p.m.

This document is a true representation of the original Certificate of Analysis.

Cecil B. Garner, President RepCo Marking, Inc.

State of Missouri DEPARTMENT OF HEALTH



MO 580-0771 (7-88)

PERMIT TYPE II



REID T FESSLER

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

DATAMASTER

for th air, is	e determination of the alcoholic sued under the provisions of s	c content of blood from a sample of expired (alveolar) ections 577.020 through 577.041, RSMo 1986.				
Date _	02/05/2010	Interim Director				
Number	200032	Director of State Public Health Laboratory Manyant T. Brandly				
Expires	02/05/2012	Director, Department of Health				
	New 17 001	Lab. 4 (R7-88)				

Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

MIŠSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL HUMBER 204112 03/01/10

ARREST TIME: 68:00
SUBJECT NAME:
TEST
DOB: 11/11/11 SEX: M
STATE/D.L.: MOVIEST
ARRESTING OFFICER:
FESSLER/R/T
OFFICER 1.D.: 992
TESTING OFFICER:
FESSLER/R/T
OFFICER I.D.: 992
PERMIT NUMBER: 200932
EXPIRATION DATE: 62/65/12
MISCELLANEOUS DATA:

--- BREATH HARLYSIS ---

RADIO INTERFERENCE

Operator Signature /

Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL HUMBER 204112 03/01/10 18:11

-- DIAGNOSTIC CHECK ---

COMPUTER:

UKHY

PROGRAM (84-87-2889):

OKRY

HEATERS

SAMPLE CHAMBER:

L.Cir.

FLOW DETECTOR:

OKAY

PUMP

HIGH SPEED:

OKHY

DETECTORS

OMAY

FILTERS:

UKSY

DURRTZ STANDARD:

UKAT

CALLERATION:

ÜKHY

PRINTER TEST

!"#\$%&'()*+.-./0123456789:;(=)?@ABCUEFG HIJKLMMOPORSTUVWXYZ[\]^_'abcdefqhajklmno pqrstuvwxyz(|)*

Operator Signature

2208-02

Face This Side Down - This Edge In First

er oak kultur sûterê yê ê bişeyê k

BAC DataMasterEvidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204112 03/01/10

TESTING OFFICER:
FESSLER/R/T
OFFICER I.D.: 992
PERMIT NUMBER: 200632
EXPIRATION DATE: 02/05/12
MISCELLAMEOUS DATA:
.10 TEST

-- SUPERVISOR NODE ---

BLANK TEST	. 608	10:15
INTERNAL STANDARD	VERIFLED	人名霍克斯
EXTERNAL STANDARD	. 999	18:16
BLAHK TEST	A CONTRACTOR OF THE PROPERTY O	18016
EXTERMAL STANDARD	. 999	18:17
BLANK TEST	A support of the supp	16:17
EXTERNAL STANDARD	(I) I I I I I I I I I I I I I I I I I I	18:18
BLANK TEST	(10) (3)	18:18

Operator Signature /

2208-02